
20.9% oxy. 0.7%/0.3% ch4
20.9 Oxy. & 2.5/ 0.4% Ch4 face
HAZ
face
face
20.9% Oxy. 1.45% ch4/
*20.9%, 0.3%
HAZ
Line Curtain
timbers
HAZ
check curtain missing
one HAZ either place
roof fall
2.5%, 20.9%
toe of roof fall
Check Curtain
CO sensor
HAZ
Tail Piece
Energized Roof Bolter
HAZ
Phone&Fire Outlet
500 ft. Fire Hose
Check Curtain
HAZ
Belt Remote Switch
Fire Extingusher
stopping with
equipment door
HAZ
PC
HAZ
Hot Bottom
Roller
Pump 1.5 HP Switch ON
Pump 1.5 HP Switch OFF
cable to pump
Belt running
HAZ
HAZ
ManDoor sign
Old Belt Fabric
ankel deep water
Pump #73
Life Line
Alternate
Primary
#1
RETURN
#2
BELT
#3
Intake