

Tri-State Post # 6
Ohio Valley Mine Rescue
Statement of Fact Test
June 5, 2013

Team Member's Name: _____

Team Name: _____

Team's Working Number: _____

1. The IDLH for Carbon Monoxide is _____ ppm.

- A. 50
- B. 200
- C. 1,200**

2. The IDLH of Carbon Dioxide is _____ ppm.

- A. 20,000
- B. 40,000**
- C. 1,200

3. A smoke tube is used to show the direction and _____ of slow moving air.

- A. Speed
- B. cfm
- C. velocity**

4. _____ is a mixture of carbon monoxide, carbon dioxide, methane, oxygen, nitrogen and hydrogen.

- A. Blackdamp
- B. Whitedamp
- C. Afterdamp

5. The _____ is the average concentration for a normal 8 hour workday and a 40 hour workweek, to which workers may be repeatedly exposed day after day, without adverse effect to a gas.

- A. TLV-TWA
- B. STEL
- C. IDLH

6. A dangerous and sometimes fatal mistake that _____ make is entering an unsafe or hazardous scene.

- A. members
- B. rescuers
- C. responders

7. “Pogo sticks” are devices which may be used to _____ temporary stoppings.

- A. construct
- B. erect
- C. build

8. Sufficient time should be allowed for a _____ area to cool before it is unsealed.

- A. seal
- B. explosion
- C. fire

9. The fresh air base should be _____ where it can be linked to the command center by means of a communication system.

- A. situated
- B. located
- C. placed

10. Surface arrangements include such tasks as _____ a command center where all decisions are made, providing an adequate information center from which all public information is released, and obtaining and distributing necessary supplies and equipment.

- A. creating
- B. securing
- C. establishing