

1 entry & X-cuts to # 2 entry

POST 5 MINE RESCUE DAY # 2

CAVED

AIRTIGHT

EXHAUST FAN

**EXHAUST FAN
SWITCH OFF**

B/O – CCA

ON SURFACE

BRAATTICE

CLOTH

**No. 1 PUMP
SWITCH OFF**

PUMP CABLE

5.5% CH₄

10 PPM CO

19.2% O₂

UNSAFE ROOF

UNSAFE ROOF

CONSCIOUS

(“HELP THE ROOF IS UNSAFE ON BOTH SIDES OF ME”)

SUMP

BATTERY

MINE PHONE

UNSAFE ROOF

UNSAFE ROOF

**PERMANENT
STOPPING
DOWN**

5.5% CH₄

10 PPM CO

19.5% O₂

LINE CURTAIN

1.5% CH₄

8 PPM CO

19.5% O₂

TEMPORARY

STOPPING

DOWN

5.5% CH₄

10 PPM CO

18.5% O₂

WATER OVER

KNEE DEEP

WATER OVER

KNEE DEEP

BRAATTICE

CLOTH

8 TIMBERS

BODY

**No. 1 STATIONARY
PUMP WITH
DISCHARGE LINE TO
SURFACE**

**WATER
ROOFED**

USED SCSR

5.5% CH₄

10 PPM CO

19.2% O₂

BARRICADE

LUNCH PAIL

USED SCSR

BRAATTICE

CLOTH

FACE

**# 2 ENTRY &
X-CUTS
TOWARD # 3**

CAVED

AIRTIGHT

CAVED

BRAATTICE

CLOTH

BATTERY

SCOOP

5.5% CH₄

10 PPM CO

19.5% O₂

WATER OVER

KNEE DEEP

**PERMANENT
STOPPING
DOWN**

CAVED

TEMPORARY

STOPPING

DOWN

BRAATTICE

CLOTH

UNSAFE RIB

COAL HAULER

4.0% CH₄

10 PPM CO

19.2% O₂

BARRICADE

4.0% CH₄

51 PPM CO

19.5% O₂

CONSCIOUS

(“HELP GET ME OUT OF HERE”)

4.0% CH₄

51 PPM CO

19.5% O₂

WATER OVER

KNEE DEEP

WATER OVER

KNEE DEEP

WATER OVER

KNEE DEEP

WATER OVER

KNEE DEEP

START OF

SMOKE

SMOKE

END OF

BARRICADE

BLOWN DOWN

**CONTINUOUS
MINER ON
FIRE**

REMOTE BOX

FACE

3 ENTRY

5.5% CH₄

10 PPM CO

19.5% O₂

CAVED

FLAGGING TAPE

5.5% CH₄

10 PPM CO

19.4% O₂

1.5% CH₄

8 PPM CO

19.5% O₂

WATER KNEE

DEEP

4.0% CH₄

9 PPM CO

19.1% O₂

WATER KNEE

DEEP

BRAATTICE

CLOTH

AIR SHAFT

FACE