


Statement 5.28.2021

- You are located in the FAB established by our responsible person about 30 minutes ago
- 9 miners are missing
- The Blowing Fan is outby no. 3 entry
- The mine maps are not up to date
- BO is in crosscut between no. 2 and no. 3 entry in the FAB


Written Instructions:

- Explore the entire mine
- Carry only 2 brattice cloths while traveling
- Blowing fan is on and cannot be stopped, stalled or reversed
- Bring all survivors to the FAB


5.28.2021 dk




5.28.2021 dk




5.28.2021 dk



5.28.2021 dk



5.28.2021 dk



Problem Keys

- Staying airlocked while working the entire problem
- Not delaying any patients while exploring
- Realizing that you can safely air through a triangle unsafe roof when you have been to all sides
- Also realizing that the barricade not airtight will not stop the explosive mix going into no. 1 entry intersection and then on to the last open xcut intersection
- Finding the quitter in last open xcut and not going past the scoop on fire from no.1 entry side and also from no. 2 entry crosscut side
- If they use fire ext. to ext. fire, discount them for not following the rules under (rule 31 B second paragraph) when a withdraw situation exists, the team is not allowed to ext. the scoop on fire
- Several map discounts could occur by not remembering where to put FPA on mine maps or by showing symbols that they never explored too because of the withdraw in no.1 entry