



LINE CURTAIN





12

TIMBERS



8 BRATTICE CLOTH



TEMPORARY STOPPING



UNSAFE ROOF



UNSAFE ROOF



5.7% CH₄
3 PPM CO
19.4% O₂



**WATER
OVER KNEE
DEEP**



**WATER
OVER KNEE
DEEP**



4.1% CH₄
3 PPM CO
19.4% O₂



4.1% CH₄
3 PPM CO
19.3% O₂



CAVED





CAVED



6.5% CH₄
1 PPM CO
19.1% O₂



BARRICADE




BODY






LIVE PERSON



BARRICADE




5.0% CH₄
0 PPM CO
17.8% O₂



**CAVED
AIRTIGHT**



**WATER
PUMP WITH
250 FEET OF**

POWER 
CABLE AND
DISCHARGE
LINE





TEMPORARY STOPPING



4.2% CH₄
7 PPM CO
19.2% O₂




CAVED




SCOOP BATTERY




BATTERY SCOOP



5.5% CH₄
8 PPM CO
19.3% O₂



BARRICADE




5.5% CH₄
8 PPM CO
19.3% O₂



CAVED



5.2% CH₄
2 PPM CO
19.7% O₂



SHAFT WALL



RETURN SHAFT



INTAKE SHAFT



SCOOP BATTERY



TEMPORARY STOPPING




5.2% CH₄
7 PPM CO
19.2% O₂



**WATER
ROOFED**



WATER ROOFED





4.5% CH₄
3 PPM CO
18.0% O₂



BARRICADE



LIVE PERSON



BODY





CAVED



CAVED



1.5% CH₄
0 PPM CO
18.9% O₂