





TEMPORARY STOPPING



5.7% CH₄
3 PPM CO
20.8% O₂



**WATER
OVER KNEE
DEEP**



**WATER
OVER KNEE
DEEP**



2.7% CH₄
7 PPM CO
18.8% O₂




**UNCONSCIOUS
LIVE
PERSON**




CAVED

CAVED






5.2% CH₄
3 PPM CO
20.8% O₂



UNSAFE ROOF




UNSAFE ROOF



**WATER
OVER KNEE
DEEP**



**WATER
OVER KNEE
DEEP**



5.8% CH₄
6 PPM CO
20.2% O₂



WATER ROOFED




WATER ROOFED



**CAVED
AIRTIGHT**



**WATER
PUMP WITH
250 FEET OF**

POWER 
CABLE AND
DISCHARGE
LINE





8 BRATTICE CLOTHS



LINE CURTAIN



12

TIMBERS



TEMPORARY STOPPING



CAVED




WATER ROOFED



**WATER
ROOFED**




UNSAFE ROOF



UNSAFE ROOF



6.0% CH₄
3 PPM CO
20.2% O₂



BARRICADE




UNSAFE ROOF



BATTERY RAMCAR




6.0% CH₄
3 PPM CO
20.2% O₂




5.3% CH₄
9 PPM CO
16.8% O₂



**WATER
ROOFED**



**WATER
ROOFED**



BODY



CAVED



CAVED



TEMPORARY STOPPING



BATTERY SCOOP



1.7% CH₄
56 PPM CO
20.3% O₂



CAVED



4.7% CH₄
2 PPM CO
18.8% O₂



BARRICADE



8 TIMBERS



UNSAFE ROOF

CONSCIOUS




LIVE

PERSON

CANNOT

WALK




UNSAFE ROOF



4.3% CH₄
2 PPM CO
18.3% O₂



BODY





CAVED



CAVED



**UNCONSCIOUS
LIVE
PERSON**



UNSAFE ROOF



UNSAFE ROOF